

Beading Foot

(BLe-BF)

instructions

Serge pearls, piping, cording, and more to the edge of fabric with ease and speed. This one-step foot will give all of your surface embellishments a professional finish.



Machine Settings

Stitch type:	3-thread rolled edge
Needle:	Right
Stitch width:	M
Stitch length:	3-4 rolled hem
Upper knife:	Engaged "UNLOCKED"
Differential feed:	N - 0.6
Sewing speed:	Slow to moderate speed

1. Remove the left needle from the machine. Set machine to narrow rolled edge. (Refer to your instruction manual for details on changing your machine to narrow rolled hemming.)
2. Replace the standard presser foot with the beading foot.
3. Stitch length setting is set between 3-4 mm, according to the size of beads used.
4. Position beads into beading foot as illustrated in Fig. A.
5. Place edge of fabric you are attaching the beads to under the presser foot, lower presser foot, and stitch.

note: It is recommended to sew a test sample before sewing your actual garment to determine the correct stitch length and test your settings.

Bead Pintucking (Flatlock on Fold):

1. Set up your machine for a 2 or 3 thread flat lock stitch (refer to your instruction manual). Disengage (or LOCK) the blade into the down position.
2. Place the folded edge of your fabric under the presser foot.
3. Insert the beads into the beading foot and position the fabric fold against the beads.
4. Sew beads to the folded edge of your fabric.
5. If you do not want to form a tuck in your fabric as you are sewing the beads to the folded edge of your fabric, use the 2 thread flatlock stitch. Sew beads to the folded edge of your fabric then pull to flatten the stitches.



Fig. A